

R500 Wire Feeder Mounting Brackets



OVERVIEW

Brackets for mounting the R500 wire feeder on the robot's 3rd axis. The set consists of two parts: top and bottom.

The top bracket is designed for the wire feeder. The bottom bracket is designed for specific robot models. Order code includes metal plates, insulation rings, and screws. Screws for the robot's 3rd axis are not included.

TOP BRACKET MODELS

SP801149 – R500 Wire Feeder Bracket, short; needed with HW robot (T1/T3)

SP801150 – R500 Wire Feeder Bracket, long; needed with HW robot (T1/T3)

BOTTOM BRACKET MODELS

The bottom bracket is a robot-specified bracket. Please ask for the product codes from sales or go to the [configurator](#).

TECHNICAL SPECIFICATIONS

R500 Wire Feeder Mounting Brackets

Product code	See technical specifications.
--------------	-------------------------------